



Entergy Nuclear Operations, Inc.
Palisades Nuclear Plant
27780 Blue Star Memorial Highway
Covert, MI 49043
Tel 269 764 2000

Anthony J. Vitale
Site Vice President

PNP 2011-073

November 21, 2011

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

SUBJECT: Licensee Event Report 2011-007, Direct Current Electrical System
Fault Causes Reactor Trip and Multiple Safety System Actuations

Palisades Nuclear Plant
Docket 50-255
License No. DPR-20

Dear Sir or Madam:

Licensee Event Report (LER) 2011-007 is enclosed. This LER describes a direct current electrical system fault that caused a reactor trip and multiple safety system actuations. In addition, an unanalyzed condition was discovered due to non-compliance with 10 CFR 50 Appendix R. These conditions are reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) and 10 CFR 50.73(a)(2)(ii)(B).

This letter contains no new commitments and no revisions to existing commitments.

Sincerely,

A handwritten signature in black ink, appearing to read "Adam Blum". Below the signature, the text "SJS BTU" is written in a smaller, less legible script.

ajv/tad

Attachment: LER 2011-007, Direct Current Electrical System Fault Causes Reactor
Trip and Multiple Safety System Actuations

CC Administrator, Region III, USNRC
Project Manager, Palisades, USNRC
Resident Inspector, Palisades, USNRC

ATTACHMENT

LER 2011-007

**DIRECT CURRENT ELECTRICAL SYSTEM FAULT CAUSES REACTOR TRIP AND
MULTIPLE SAFETY SYSTEM ACTUATIONS**

3 Pages Follow

LICENSEE EVENT REPORT (LER)

(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOF-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

PALISADES NUCLEAR PLANT

2. DOCKET NUMBER

05000255

3. PAGE

1 OF 3

4. TITLE

Direct Current Electrical System Fault Causes Reactor Trip and Multiple Safety System Actuations

5. EVENT DATE

MONTH DAY YEAR

09 25 2011

6. LER NUMBER

YEAR SEQUENTIAL
NUMBER REV
NO

2011 - 007 - 00

7. REPORT DATE

MONTH DAY YEAR

11 21 2011

8. OTHER FACILITIES INVOLVED

FACILITY NAME DOCKET NUMBER

FACILITY NAME DOCKET NUMBER

9. OPERATING MODE

1

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)

- | | | | |
|---------------------------------------------|---------------------------------------------|--------------------------------------------------------|--------------------------------------------------|
| <input type="checkbox"/> 20.2201(b) | <input type="checkbox"/> 20.2203(a)(3)(i) | <input type="checkbox"/> 50.73(a)(2)(i)(C) | <input type="checkbox"/> 50.73(a)(2)(vii) |
| <input type="checkbox"/> 20.2201(d) | <input type="checkbox"/> 20.2203(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(viii)(A) |
| <input type="checkbox"/> 20.2203(a)(1) | <input type="checkbox"/> 20.2203(a)(4) | <input checked="" type="checkbox"/> 50.73(a)(2)(ii)(B) | <input type="checkbox"/> 50.73(a)(2)(viii)(B) |
| <input type="checkbox"/> 20.2203(a)(2)(i) | <input type="checkbox"/> 50.36(c)(1)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(iii) | <input type="checkbox"/> 50.73(a)(2)(ix)(A) |
| <input type="checkbox"/> 20.2203(a)(2)(ii) | <input type="checkbox"/> 50.36(c)(1)(ii)(A) | <input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A) | <input type="checkbox"/> 50.73(a)(2)(x) |
| <input type="checkbox"/> 20.2203(a)(2)(iii) | <input type="checkbox"/> 50.36(c)(2) | <input type="checkbox"/> 50.73(a)(2)(v)(A) | <input type="checkbox"/> 73.71(a)(4) |
| <input type="checkbox"/> 20.2203(a)(2)(iv) | <input type="checkbox"/> 50.46(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(v)(B) | <input type="checkbox"/> 73.71(a)(5) |
| <input type="checkbox"/> 20.2203(a)(2)(v) | <input type="checkbox"/> 50.73(a)(2)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(v)(C) | <input type="checkbox"/> OTHER |
| <input type="checkbox"/> 20.2203(a)(2)(vi) | <input type="checkbox"/> 50.73(a)(2)(i)(B) | <input type="checkbox"/> 50.73(a)(2)(v)(D) | Specify in Abstract below or in
NRC Form 366A |

10. POWER LEVEL

98

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME

Terry Davis

TELEPHONE NUMBER (Include Area Code)

(269) 764-2117

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX
B	EJ	BKR	G190	Y					

14. SUPPLEMENTAL REPORT EXPECTED

☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO15. EXPECTED
SUBMISSION
DATE

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On September 25, 2011, at 1506 hours, during planned maintenance activities on a direct current (DC) electrical distribution (ED) panel, ED-11-2, a short circuit fault between the positive and negative bus bars was introduced into the system. The fault was caused by the accidental contact between bus bar connectors within the panel. Subsequently, a partial loss of DC electrical system power occurred, causing an automatic reactor trip and multiple safety system actuations.

The fault from ED-11-2 propagated upstream, resulting in a loss of left train DC power to two-of-four inverters and subsequent loss of alternating current (AC) power from the inverters to two-of-four preferred busses. The loss of power initiated a reactor trip via the automatic actuation of the reactor protection system (RPS). Additional automatic actuations include the closure of the main steam isolation valves (MSIVs), actuation of the safety injection system (SIS), actuation of the containment isolation system (CIS), and actuation of the auxiliary feedwater system (AFS). The MSIVs, RPS, SIS, CIS and AFS performed as designed for the loss of power condition.

The root cause of the event was attributed to risk management processes not being followed, resulting in the failure to adequately manage the risk associated with the maintenance on the ED-11-2 panel. In addition, there was insufficient breaker and fuse coordination for the left train of the 125 volt DC system. An engineering change was approved and installed to reduce the probability of recurrence. Repairs to the affected DC electrical system components were completed and the reactor was returned to full power operation on October 3, 2011.

(10-2010)

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
PALISADES NUCLEAR PLANT	05000255	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 3
		2011	- 007	- 00	

EVENT DESCRIPTION

On September 25, 2011, at 1506 hours, with the plant in Mode 1 at approximately 98% power, during planned maintenance activities on a direct current (DC) electrical distribution (ED) [EJ] panel, ED-11-2, a short circuit fault between the positive and negative bus bars was introduced into the system. The fault was caused by the accidental contact between bus bar connectors within the panel.

The fault from ED-11-2 propagated upstream, resulting in a loss of DC power from the associated DC bus to two-of-four inverters. The loss of DC power to two-of-four inverters caused a loss of alternating current (AC) power from the inverters to two-of-four preferred busses. The loss of power initiated a reactor trip via the automatic actuation of the reactor protection system (RPS). Additional automatic actuations include the closure of the main steam isolation valves (MSIVs), actuation of the safety injection system (SIS), actuation of the containment isolation system (CIS), and actuation of the auxiliary feedwater system (AFS). The MSIVs, RPS, SIS, CIS and AFS performed as designed for the loss of power condition.

There were no inoperable structures, systems, or components at the start of this event that contributed to the event.

The event is reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in the actuation of multiple safety systems and 10 CFR 50.73(a)(2)(ii)(B) as an unanalyzed condition due to non-compliance with 10 CFR 50 Appendix R.

CAUSE OF THE EVENT

The root cause of the event was attributed to risk management processes not being followed, resulting in the failure to adequately manage the risk associated with the maintenance on the ED-11-2 panel. In addition, there was insufficient breaker and fuse coordination for the left train of the 125 volt DC system.

The 125 volt DC system is divided into two independent and isolated systems, left train and right train. In 1981, a circuit breaker [BKR] with a shunt trip device was installed in each independent train. The shunt trip device is a trip coil that, when energized, allows opening of the breaker remotely. The purpose of the breaker is to prevent battery drain from ground faults in the DC system due to fires in the plant's cable spreading room.

The breakers, 72-01 in the DC system left train and 72-02 in the DC system right train, were designed to be non-automatic, manually operated, with the capability of being opened remotely via the shunt trip device. Per the site's licensing basis documentation, the breakers were not intended to interrupt fault currents, although they have that capability. Contrary to the site's design and licensing basis documentation, the breakers contained an automatic trip feature that caused breaker 72-01 to trip open due to the over-current produced from the short circuit condition on September 25, 2011.

The as-found automatic trip set-point of shunt trip breaker 72-01 was too low to demonstrate acceptable 10 CFR 50, Appendix R, electrical coordination. The automatic trip set-point of shunt trip breaker 72-02 was found at the maximum value. It was determined that the maximum value, for the breaker's automatic trip set-point, is acceptable for 10 CFR 50, Appendix R, electrical coordination.

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
PALISADES NUCLEAR PLANT	05000255	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 3
		2011	- 007	- 00	

CORRECTIVE ACTIONS TAKEN

In response to the event, an Entergy corporate event response team (CERT) was dispatched to Palisades to independently review the causes and contributors to the event with a special focus on the organizational and programmatic aspects. Based on the findings identified by the CERT, Palisades has implemented a site recovery plan to correct significant behavior and performance gaps at all levels of the organization.

The damaged bus bar connectors in the ED-11-2 panel were replaced.

Guidance for work on energized circuits was issued to assist in the identification of situations that could result in an industrial safety risk activity or a potential plant shutdown.

To reduce the probability of recurrence, an engineering change was approved and installed raising the automatic trip set-point of shunt trip breaker, 72-01, to the maximum value and allowed shunt trip breaker, 72-02, to remain at the maximum value. Compensatory measures were implemented that administratively prevents work from being performed on the affected DC electrical distribution panels, and cables within the cable spreading room connected to the affected DC electrical distribution panels, when the associated DC bus is required to be operable. Additional compensatory measures were implemented that allow only one battery charger to be connected an operable DC bus and the opening of breakers in the affected DC electrical distribution panels that supply power to non-safety related loads.

CORRECTIVE ACTIONS TO BE TAKEN

A training needs analysis will be performed to determine the appropriate performance improvement intervention to be implemented that will ensure risk management processes are adequately incorporated into the work planning process and risk is appropriately managed.

An engineering change will be implemented to permanently correct the coordination issues with shunt breakers and their respective DC system electrical distribution panel fuses.

ASSESSMENT OF SAFETY CONSEQUENCES

No actual safety consequences resulted from this event. System response was as expected given a loss of one train of DC power. The SIS operated but did not inject since primary coolant system pressure remained above shutoff head. The right train of DC power remained available throughout the event. The occurrence of the short circuit fault in the DC panel and actuation of the over-current trip of the shunt breaker represents the worst consequence for failure of one train of DC power.

PREVIOUS SIMILAR EVENTS

None